

Castelmann

5c.12.16.

F.E.

Received by Chief Ship Surveyor 22.4.18

Received from Chief Ship Surveyor _____

VESSEL'S NAME Shells John Jacobs Rpt. Shel No. 30480

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 37.12

Depth "d" 12.16

Framing: Table No. 3 page 10 Description Single angle as approved

Longitudinal No. 5734

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.24$

~~Deck~~ Sheerstrake - 62 of an inch instead of 38 as reqd

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A-1 (Steel) Steam Tug as recommended.

1 Dk. (Steel)
BK 7 1/2 4 BH. Cam. Lysacep. Q277. F19

M
22.4.18



© 2020

Lloyd's Register
Foundation

005141-005153-0130