

Rpt. 9A REPORT OF MACHINERY SURVEYS AND REPAIRS (ENGINES AND AUXILIARIES)

Received London
13. AUG.

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Ship's Name ~~SS/MS~~ "TASSIA" (LR.501914)
 Gross tons 2321 Port of Registry Piraeus. Port HULL.
 Date of build 1944 Is there a rpt. 8? Yes. Forwarded Rpt. No. 70744
 No. of visits 3 First date 27.7.65. Last date 29.7.65.
 Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? No. Last rpt. (H.Q. only)
 Date of completing rpt. 5.8.65. Surveyed at, if different from Port above -
 Is a rpt. 9B attached? No. MN 306 Nature of survey E.S. Completion.
 Survey fees E.S. £5.0.0d. Damage fee Expenses 12/-
 S.A. fee

MAIN ENGINES, RECIP., STEAM OR I.C. (State Port—P or Starboard—S)

- 1 Cyls., covers, pistons & rods
- 2 Valves & gears
- 3 Con. rods, cross-heads, bearings & guides centre Side
- 4 Crankpins & bearings centre Side
- 5 Journals & bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS (State Port—P or Starboard—S)

- 6 Cyls., covers, pistons & rods
- 7 Con. rods, cross-heads & bearings
- 8 Crankpins & bearings
- 9 Journals & bearings
- 10 Coolers & safety devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS (State Port—P or Starboard—S)

- 11 Cyls., covers, pistons & rods
- 12 Con. rods, cross-heads & bearings
- 13 Crankpins & bearings
- 14 Journals & bearings

MAIN TURBINES (State Port—P or Starboard—S)

- 15 Casings, rotors, blading, bearings, & thrusts
- 16 Reduction gearing
- 17 Scavenge blowers
- 18 Superchargers

I recommend that the machinery of this ship remain as classed ~~with~~ without fresh record of E.S. 5,65 as previously recommended subject to any conditions which may be attached to the ships class remaining as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Surveyor to Lloyd's Register of Shipping

Date of Committee

Minute

FRIDAY - 3 SEP 1965

Deferred for comp MBS
ES 5.65 subject

ALSO FOR

SPL FOR

TRO

NOTED BY
CESR

POSTING

HEADER

CERT

005174-005179-0292

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subject to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

Considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

20 Exhaust steam turbines (with recip. eng.)	21 Thrust blocks shafts & bearings	
22 Steam compressors	23 Intermediate shafts & bearings	
24 Clutches & hydraulic couplings	25 Condensers (main & aux.)	
26 Steam re-heaters	27 Air ejectors (main & aux.)	
28 De-superheaters	29 Forced &/or induced draught fans	
30 Stop & manoeuvring valves	31 Holding down bolts & chocks	32 Detuner or vibration damper
33 Main engine driven pumps		

State
Port P. or
Starboard S.

34 Crankcase doors & explosion relief devices

35 Have main engines been tested working & manoeuvring? (To be done on completion of ES or CS cycle)

36 Essential independent pumps -

37 Bilge, ballast & oil fuel suction lines, fittings & controls

38 Have the remaining piping arrangements & fittings in the machinery space been examined as considered necessary?

39 Fresh water coolers

40 Lub. oil coolers

41 Heaters (state service)

42 Feed water filters

43 Auxiliary air receivers & safety devices

44 Starting air pipes

45 Main air receivers & safety devices

46 Independent air compressors coolers & safety devices

47 Oil fuel tanks (not forming part of the hull structure)

48 Have all evaporators safety valves been tested under steam?

49 Evaporators HP & LP

50 Distillers

51 Fire extinguishing arrangements

52 Steering machinery

53 Windlass

Identify
by
position

AUXILIARY ENGINES

Diesel auxiliary generator engine. - Good.

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.


CONDITION OF CLASS.

The Owners representative stated that the earliest possible time that the safety valve springs could be obtained was 10 weeks and that they had already been ordered.

The vessel left this port without any other condition being dealt with.

It is therefore recommended that all conditions remain as previously recommended.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should also be reported above.



© 2020

Lloyd's Register
Foundation