

Subject:- to a keel plate and indented shell plating etc, on starboard side forward being dealt with at the Owners' convenience.

Hts. 1789

11

Received by Chief Ship Surveyor 3.3.34

Received from Chief Ship Surveyor 7 - MAR 1934

VESSEL'S NAME *Steel Ss* "BAHRAM" Rpt. *Msl.* No. 8424.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

The *Marseilles*

Surveyors report this vessel placed in

dry dock, bottom cleaned and coated and minor repairs effected.

The indented keel + shell plating, as above, examined and found satisfactory.

It is submitted the vessel appears worthy to remain as

classed with record of survey

subject as above
2.34 *L* as recommended.100 A.1. } *subject etc.*2.34 *Msl**Carrying petroleum in bulk.**Fitted for oil fuel etc**Regsk.*

© 2020 6.3.34

Lloyd's Register
Foundation

005180-005186-0096