

P.S. "City of Durban."

Hull. 33135.

While this vessel was undergoing a steaming trial in dock last March damage occurred to the machinery from an unknown cause resulting in partial destruction of the gearing and damage to the turbine blading and bearings and also to the condenser.

The machinery was removed to the shops, and has been renewed or repaired as necessary, and a satisfactory steaming trial held.

It is submitted that  
this vessel is eligible for  
**THE RECORD.**

† L. M. C. - 1.22. C. L. F. D.

607 N.H.P.

Fitted for Oil Fuel, 1.22., F.P. above 150° F.

2 steam turbines geared to one screw shaft.

L. Hull 10/1/22

L. G.  
© 2020

It is concluded that the screw shaft is fitted with a continuous liner, but this should be confirmed.

005180-005186-0276

Working pressure by rules

Steam dome: description of joint to shell

of strength of joint

Thickness of shell plates

Material

Description of joints

of strength of joint