

3 NOV 1966

Ship's name

JW

"KORCULA"

Port

Split

No.

2746

Last survey date 5.10.66Class is subject to

For conditions of class see previous endorsement.

S.R.L. Appendix (~~as before or~~ none)Nature of present survey (afloat and in drydock)

Docking.

Deferred repairs due to contact damages.

Repairs to S.R.L. items as above.

RecommendationSUBMITTED record of DS 10,66 be assigned,
without special conditions.

DS 10,66 Without?

INSERT IN S.R.L. APPENDIX

(Stem bar buckled at 11' draught mark).

Bottom shell plate B.2 (p.f) indented.

TO NOTE		TOO
S. PL.	RESEARCH	S. DEV. LOP.
FREEBOARD	E. REPORTS	PUBS.

IT IS FURTHER SUBMITTED the Surveyors be advised
it is concluded the indented shell plate No.2 from forward
(p) recommended to be entered in the S.R.L. Appendix is shell
plate A.2 but confirmation is desired.

B.2. see
B.2. 14/4/66

7/11

21-10-66