

S.....MITRA.....

IT IS SUBMITTED theROTTERDAM.....
 surveyors be informed in reply to their letter of4.7.62
 that, according to the records in this Office, the
 following remains to complete the Continuous Survey
 cycle of the machinery at this date. It should be
 borne in mind that delay in completing the Survey
 may involve the examination of additional items.

Examine:-

NOS. 2 6 7 8 CYLS. PISTONS RODS VALVES & GEARS.

NOS. 1, 2, 4, 5, 7 8 CONNECTING RODS TOP ENDS
 & GUIDES

NOS. 1 4 2 CRANKPINS & BRGS. SUPERCHARGER

NOS. 3 5 7 9 JOURNALS & BRGS.

THRUST. H.D. BOLTS & CHOCKS

CRANKCASE RELIEF DEVICES

ENGINE TEST

ATTACHED) BILGE & FW COOLING PUMPS

AND) BILGE, FUEL TRANSFER, LUB. OIL, F.V. COOLING
 AND FEED PUMPS

PUMPING ARRGS

EVAPORATOR & ITS SVs

SEPARATE OF TANKS

STEERING MACHIN. WINDLASS. FIRE EXT. ARRGS.


AND) AIR COMPRESSOR DRIVEN BY AUX. ENGINE

AND) AUX. AIR RECEIVERS

TEAM AUX. ENGINE

AUX ELECT. EQUIPMENT

AND) HRS. OF OIL BURNING ARRGS



© 2020

Lloyd's Register
 Foundation

657
 m Pipes
 are