

Chief Surveyors 8-818

Received from Chief Surveyors

SHIP'S NAME *Stuessa Santa Olivia*

Report *Ph*

No. 2906

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

of Survey

When due

100 A-1. (Steel) Shells dx with foreboard

2 dxs (Steel) & Shells dx (Steel) 3 dx (Steel) & No. 1 hold only.

Web frames Longitudinal framing.

Cell 5.B. 346. 12095. D.T. 32' 8266 F.P.T. 715. C.P.T. 166

FK. 6.B.H. Cen ax CP. For Shells dx 31'

It is enclosed the rivets in No 9x10 longitudinal are spaced
5 dia. as in the sister vessels, but the Surveyor should
state if this is so

005301-005306-0061