

1.

Sent to Chief Surveyors 5. 12. 05

Received from Chief Surveyors

VESSEL'S NAME *St. L. S. Commandant*Report *Es.*

No. 233 14

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

*Fit entry**When due**Calculated  
23248*

+ 100 A1 ("Steel")

1 Dr (St) Mill bank.

N.B = FPT 27c

FK 7" 3BH Cam. Lloyd's A&amp;LP Q46' B7' F19' Mchly Aft.

*C. H. P.  
5/12/05**D. 114 T*

© 2021

Lloyd's Register  
Foundation

005311-005317-0208