

2m, 8, 12.

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME STEEL S.S. "ST. HILARY" Report Liverpool No. 79870

**For the CHIEF SHIP SURVEYOR** ~~FOR THE CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

A.1. (steel) "For Towing Purposes".

1 Ok. (steel)

Cell DB a. 17' 19t.

FPT 26t. APT 38t.

BKG. 3BH.

Conn. Lloyds A.Y.C.P.

F32.



*[Handwritten signature]*

© 2020  
AES  
25-11-19

Lloyd's Register  
Foundation

*W.P. 2/12/1919.*

The Surveyors should be requested to forward the usual Ship Forgings & Castings Repairs.

005325 - 005336 - 0034