

4E

170 MAR 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME "SCALBY WYKE" REPORT Hul. No. 63769.

MBS due 5.58, now held.

Docking. Screwshaft seen. Boiler repairs carried out and boiler hydraulically tested on completion, re-examined under steam and found satisfactory.

IT IS SUBMITTED that this vessel is eligible for THE RECORDS,
 MBS 2.58,
 TS CL 2.58.



© 2020

Lloyd's Register
 Foundation

5.3.58.



005344-005352-0193