

A.N

T.2 tanker

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP NAME "MESA VERDE" REPORT Gls. No. 72358For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey Docking and General Exam- When due.....  
nation.

Indented shell plating in way of Nos. 9 & 7  
 tanks (s.s) and No.3 (p.s) require to be dealt with, and  
 60 fathoms of chain cable require to be supplied.

100A1 (Classification Contemplated)  
 "Carrying Petroleum in Bulk"

ls. 12.47., subject.  
 Examined 12.47"

ADM.  
 4-1-48.

*The Surveyors should be requested to  
 state if this usual has been cut & strapped.*

NOTE:

Anchors and chain cables have been ~~examined~~ **RANGED**  
 and verified with certificates. Anchors are  
 three grades up.



(56)



© 2021

Lloyd's Register  
 Foundation

005377 - 005386 - 0295