

10m/11.20

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME Steel S.S. "SAN FELIX". Rpt. Nwc. No.74521.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


of Survey

This vessel was classed 100 A.1. "Shelter deck with freeboard" on the 29th July last, when it was concluded the scantlings and arrangement of the forecastle deck were in accordance with the approved plan, and the Surveyors were requested to state if this was so.

The Surveyors in reply stated that the Builders regretted that the beams had not been fitted in accordance with the approved plan, and proposed to fit compensation to the existing forecastle beams at the first opportunity, and also to do the same in the case of the Sister vessel now building.

A plan shewing the proposed compensation has been forwarded and approved.

In the circumstances, in view of the certificate for classification not having yet been issued, it is submitted the class should be subject to compensation, as approved, being fitted to the forecastle deck beams at the first opportunity.



© 2020

Lloyd's Register Foundation

005387-005396-0211