


SS. "San Felix"

It is concluded the Screw Shaft of this vessel
is fitted with a continuous liner, and that
2 Spare bucket & rod have been supplied
for the Lubricating oil Circulating pumps.
but it is submitted the Newcastle
Surveyors be requested to state whether
this is so.



© 2020

R.C.M.

28/7/21

Lloyd's Register
Foundation

005387.005396.0322