

"M/T. SKANDINAVIA"

See Sect. Letter "S" dated 5th June 1940, addressed to Pres. Surveyor New York with a view to vessel receiving the Society's Class.

Now Done. General Examination

Additional to the foregoing examination, the dry cargo hold, peaks, tween decks, deck erection spaces, pump room and machinery spaces generally examined. The cargo tanks and cofferdams generally examined internally. Double bottom fresh water tanks opened up, cement washed and generally examined internally. Decks & casings, masts & rigging, boats, general equipment, hatchways, hatches & battering arrangements, ventilators & coamings, air & sounding pipes, steering gear & windlass (also tested under working conditions) all generally examined & found in good condition, and the workmanship and materials so far as now seen, good & to my satisfaction.

The scantlings and arrangements verified, checked, & so far as seen, found in accordance with the particulars shown in Rpt 1 forwarded herewith
Lionel Rennie.

Cert B issued, 2 copies (inc.) herewith.



© 2020

Lloyd's Register
Foundation

0099 2/2