

Chief Ship Surveyor

Received from Chief Ship Surveyor

24 JAN 1939

NAME

"ILONA"

Rpt.

Msl.

No.

9750

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

11/15/39 (3/38.)

The class is subject to shell plate B9 (p.s.) indented, being dealt with at the Owners' convenience.

The Marseilles Surveyors report the vessel placed in dry dock, bottom cleaned and coated.

The indented shell plate B9 (p.s.) as above specially examined and found efficient.

It is submitted the vessel appears worthy to remain as classed with record of survey 12,38, subject as above.

100A1
12,38 Msl. } Subject etc.



© 2020
16.1.39

Lloyd's Register
Foundation

005489-005502-0209