

F.E.

Received by Chief Ship Surveyor 6.8.14

Received from Chief Ship Surveyor

VESSEL'S NAME

Shells OtlicheRpt. 1stNo. 27798

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 35.41Depth "d" 12.25Framing: Table No. 3 page 10Description Single Angle as approvedLongitudinal No. 4143

Proportions

Length

Depth

8.6~~Deck~~ Sheerstrake 56 of an inch instead of 34

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A-1 (steel) Steam Trawler, as recommended

100 A-1 (steel) Steam Trawler1stBK 7 1/2. 4BK. Can. Legs over Q 6'

© 2020

Lloyd's Register
Foundation

005537-005551-0077

Tee Butt, or Channel
Angles on upper edge

Angle on ditto

Tie Plates