

1

Sent to Chief Surveyors 2. 6. 23.

Received from Chief Surveyors 6 - JUN 1923

VESSEL'S NAME S.K. "Malen"

Report Lon.

No. 86703^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

Boiler

When due

4. 22

Screw Shaft 9. 22.

To complete the boiler survey due 4. 22 & partly held in 12. 22 the safety valves require to be adjusted. The examination of the screw shaft became due in 9. 22.

The Bilbao Surveyors now state that they are in receipt of a communication from Senor don Luis Kamiqueira of Madrid, in which he states that he does not desire to continue his steamer "Malen" in this Society's class.

It is submitted the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the request of the Owner.

Withdraw class.
Insert ...

C.S. J.R.D.
2/6/23



© 2020

Lloyd's Register
Foundation