

Ship Surveyor .....

Received from Chief Ship Surveyor .....

NAME *Stal S.S. 'ORSINO'*

Rpt. *Hul*

No. *32727*

s of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

e endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also  
o bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points  
resented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

vey

understood this vessel has proceeded to Rotterdam for repairs  
Submitted the Rotterdam Surveyors be requested to state the frame spacing  
nd of  $\frac{3}{8}$  length amidships & in the peaks and the Stanchions of the 2<sup>nd</sup> deck  
gh beams

*M*

*AD*

*2.8.21*



© 2020

Lloyd's Register  
Foundation

005791-005810-0360