

Way of ...
6 3 1/2 50

3m. 2, 24.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

S.S.M.V. "Asuka Maru"

Report

Gls.

No. 44142.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/42.)

Nature of Survey

1st Entry

When due

Revised Rules.

+ 100 AI (Steel)

2 Dks. (Stl.) 3rd DK (Stl.) in No 1 + 3 holds.

Cell. D.B. 375' 1408t. D.T. a 27' 899t. F.P.T. 140t. A.P.T. 75t.

F.K. 8 B.H. (IBH. to 2nd Dk) Lloyds A.H.P. F 42'

The Surveyor should be requested to state if cement is fitted in the bilges speaks & also if fitted in any other parts of the vessel.



© 2021

13-11-74

Lloyd's Register Foundation

005840-005848-0021

spacing