

s/s "Kovda"

Bgn 1685.

It is submitted the Bergen Surveyor be informed it is concluded that the diameter of the S.D cylinder is  $18\frac{3}{8}$ " as submitted on the plans & the diameter of the screw shaft is  $11\frac{1}{2}$ " as approved & is fitted with an oil gland at the outer end of the stern bush.

The Surveyor should be informed that the machinery <sup>& electric light</sup> report forms used in this case are obsolete & future cases should be reported on up to date forms.

On 9/1/25 yes.

See Bgn. ltr. 19/1/25

W.D. 7/1/25  
Lloyd's Register Foundation  
005481-005994-0134