

Is a special damage report he is required to state whether he offered his services for the

Was a damage report made by anyone else? If so, by whom?

d?

Turbine S. S. George

New Bammel Laird Harb No 665.

Liverpool Report No 58263.

Plans attached :-

1. Midship Section
2. Profile Deck plan.
3. Long, Main & Lower Decks.
4. Rigging plan
5. Shaft brackets
6. Mast plan
7. Pumping plan.
8. Stern frame.
9. Rudder
10. Engine Beating
11. Steering gear
12. Cast steel tiller
13. Details of B frame.
14. Three plans of ballast tanks in fore hold.
15. Plan of fore end of fore boiler room.
16. Two Boiler plans
17. Two Plans of Steam Pipes
18. Modification to stays in Boilers.
19. Three plans of Water

Items :-

Copper  
(S)  
W

Boats

Masts

Condi

(S)

Sails

Equi

Anch

Cabl

"


"

Haw

Stan

el in

emai



© 2020

Lloyd's Register  
Foundation

006111-006125-0177