

to Chief Surveyors

29. 6. 18

Received from Chief Surveyors

VESSEL'S NAME

Sheels War Viceroy

Report

Portland

No. 476

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

ture of Survey

1st Eng-

When due

The original Owners have furnished a letter agreeing to the omission of the intermediate bulkheads (attached to 1st entry report of the S.S. "War Baron".)

❖ 100A-1. (Steel)


2 DXs (Steel)

Cell D.B. 356' 1140L F.P.T. 128L A.P.T. 143L

FK. "Intermediate Bulkhead in fore + after holds dispensed with. 5 BHs only. A+P. P44' B115' F47.

3.18 low.

"pt. cem."



© 2021

Lloyd's Register
Foundation