

F.E.

Received by Chief Ship Surveyor

23/3/12

Received from Chief Ship Surveyor

VESSEL'S NAME

M. S. I. Victoria

Rpt.

Grab

No.

7244

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

34.33

Depth "d"

11.16

Framing: Table No.

3 page 9

Description

Single angle as

Longitudinal No.

4119

Approved

Proportions

Length =

9.6

Depth =

Deck Sheerstrake

16 in excess of the Rule requirements.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100A-1. (Club) Steam Trawler as

recommended.

$\pm$  100A-1. (Club) Steam Trawler

18x

BK 7 $\frac{1}{2}$  3BH Gen. Lloyd's at 60 269 F 20



© 2021

Lloyd's Register  
Foundation

006204-006220-0172