

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "WILLIAM. PENN."

Report

PL.

No. 4190**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

✱ 100. A-1. (Steel) "Shelter DK with foreboard"

1 DK (Steel) & Shelter DK (Steel) and 2nd DK (Steel) forward Webframes

longitudinal framing

Cell IB 345' 1412t, MT 24' 944t, ITa 12' 48t, FPT 235t, APT 268t
 FK, 6BH to Shelter DK 2 BH to Upper DK, pt. Low, A.C.P.,

Date of build 3.21.

P41' B134' F46' at Shelter DK



© 2020
 Lloyd's Register
 Foundation

006221-006235-0020