

Lap of plates or width of butt straps 17 3/4 Per centages of strength of longitudinal joint rivets 85.75 plate 94.4

S.S. Gangnil II Son. Rpt No. 11412

It is submitted the Son. Champton Surveyors be requested to state whether the screw shaft of this vessel, examined by them on 13/10/42, runs in oil and is fitted with an approved oil gland at its after end.

The Surveyors should be informed that in all future cases when reporting surveys on vessels whose screw shafts run in oil and are fitted with approved glands, or other approved appliances, the type of gland should be stated on the report.

006236-006247-0138

Dates During progress of work in shops

Is the approved plan of boiler for