

F.E.

Chief Ship Surveyor 2.7.17 Received from Chief Ship Surveyor _____

NAME Sheels Nagans Mani Rpt. Rag No. 1129

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 79.08 Depth "d" 17.5

Table No. 3, page 15 Description Channels as approved

Longitudinal No. 27282

Proportions Length = 11.86
Depth = _____

Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the plans and the approved plans, and it is submitted she is eligible to be classed 100 A-1 (Steel) as recommended.


25% (Steel)

Call DB 294 772 E. A.P.T. 27 E

FK. 6 B14. Can Lloyd's cert. P33. B74 F40

M
3.7.17

It is considered the intermediate bulk and lower frames in, call DB are in the same state of charge as the lower



© 2020 Lloyd's Register Foundation

006364-006386-0282