

Port

Vessel's Name *Robin Adair*

Ins. 12.20

1

Chief Surveyors

Received from Chief Surveyors

NAME *Stal S.S. "ROBIN ADAIR"* Report *Seattle* No. *962*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Survey When due

*✠ 100 A-1 (Stal) "Shelter DK with freeboard" } Subject to the Requirements
2 Dks (Stal) + Shelter DK (Stal) } of Sec 49 of the Rules being
Complied with
Cell DB 358' 1222t DTa 35' 81t FPT 91t APT 200t
FK 3BH to Shelter DK 4 BH to upper DK, pt. Cen, A + CP.*

Fitted for oil fuel 1.70 FP above 150° F

M
PD
22-1-21



© 2020

Lloyd's Register
Foundation

006387 006400-0082

Particulars for Record in Register Book. } Freeboard 8 ft. 11 ins.
} Corresponding Draught 27 ft. 6 ins.

date