

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S/S "JOULE" Rpt. Hul. No. 33676

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

Dimensions 115' x 22' x 13'

Scantling Nos. 35 and 4025

Proportions 8.84 depths to length.

This vessel built in 1918 under the Survey of the British Corporation is of the "Strath" type trawler.

An examination of the vessel has now been made and the scantlings checked with approved plans and forwarded in a first entry report.

The scantlings and arrangements appear generally to be in accordance with the plans approved for this type of vessel.

A Special Survey No. 1 has been carried out, the requirements of section 48 of the Rules complied with and a favourable report received from the Surveyors.

The vessel appears worthy to be classed :-

100 Al (steel) "Steam Trawler"
1 Dk.
DBf 29' 19t.
BK 7½" 3 BH Cem. Lloyds A & C. P.
Date of build 1918
9.22 Hul.
SS Hul No. 1.22

15-9-22

© 2020

It is concluded the test applied to the Ledge anchor is as required by the Rules but the Surveyor should be requested to state if this is so.
Yes
L 26/9/22