29707.

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

When received in London Office ___ 4 DEC 1928

Port __Kobe__

Vessel's Name __"KYOKKOH MARU" (Ex- YPRES MARU")__

Official No. __26830__   No. in Reg. Book __90752__

Port of Registry (For Foreign Vessels) __Kobe__

Iron or Steel __Steel__   State whether Classed by Lloyd's Register __Yes__

Name of Owners __Yamashita Kisen KK.__ Date of Verification __16th October, 1928__

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions :—

From centre of disc to top of statutory deck line	9 ft.	3½ ins.
From centre of disc to top of statutory deck line at awning or part-awning deck . . . }	ft.	ins.
Fresh Water line above centre of disc . . .		7 ins.
Indian Summer line above centre of disc . . .		6½ ins.
Winter line below centre of disc		6½ ins.
~~Winter North Atlantic line below centre of disc~~		ins.

Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of ~~wood or~~ steel deck with the vessel's side } at ~~main, spar or upper dk.~~ _shelter deck_   1¾ ins. _from steel deck_

at ~~awning or pt. awning dk.~~   ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or steel deck.

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales :— ___

Y. Jo.   Ass't Surveyor.

___

(To be filled up in London Office.)

Statement No. __29707__ Date of Committee's Minute __26. 1. 29__

Particulars for Record in Register Book. { Moulded Depth . . . __37 ft. 6 ins.__
Freeboard . . . . . __9 ft. 3½ ins.__
Corresponding Draught __28 ft. 7 ins.__

Freeboards compared and found correct by _____ Date __7.12.28__

Is fee paid ?   Form for Certificate

Instructions   Date

Certificate written __7/12/28__   Noted for posting

2m,11,23.

006666 - 006679 - 0156

* If the frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.