Rabat

1.

Sent to Chief Surveyors 13. 5. 02 Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "Clarence". Report Gls. No. 19866.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in conection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey 1st entry When due

✠100A1. ("Steel").
1Dk (Stl). "Well deck".
WB = F'PT. 60t. APT 5t.
Q 91'. B 10'. F 25'. Mchy aft.
BK 7¼". 3 BH. Cem. Lloyd's A & C P.

J. H. T.
13/5/02.

Additional Midships fitted Jan[y] 1905
see Hull 16603.
After peak bulkhead extended to Rack Nov[r] 1905
see Hull 17361

© 2021 Lloyd's Register Foundation
006731-006740-0143

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| " " in Hold " " | 3 | 42 | | 3 | 42 | | " Angle on ditto | | 3 X 3 |
| WEB FRAMES, In Engine Room | | | | | | | " Tie Plates | Centre plate | |