

WB=CellDBorDBa feet; uE&B
total capacity tons. FPT tons; APT
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 11371 Port 1/4

RVEYS.

(Periodical Surveys, when held, must be reported in detail and serial complete the Surveys should be summarised. State clearly the extent of Examinations and subsequent repairs. Repairs on should be separated from Repairs due to other causes; and summarised in the form shown below. Whenever the report should be clearly stated in the space provided on the back of this case.

No. 2095 where the St. Bk. 5873 tons, Built 1920-11 mo

Classed +100A1 Owners Jamai Syosen K.K.

Port of Registry Hasidate

Survey Due B.S. due 2.42.

Committee's Minute THE 2 JUN 1942

Decision OMIT CLASS
ON RE-PRINT.



© 2021

Lloyd's Register
Foundation

006731-006740-0274