

Rpt. 12.

Yard No. 271. 25902.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

1913

Port *Nagasaki*

When received in London Office 17.6.18

Vessel's Name *Arabia Marn*Official No. *✓*No. in Reg. Book *✓*Port of Registry (For Foreign Vessels) *Osaka*Iron or Steel *Steel* State whether Classed by Lloyd's Register *yes*Name of Owners *Osaka Shosen Kaisha* Date of Verification *29 Apr. 1918*

351. I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	<i>✓</i>	ft.	<i>✓</i>	ins.	<i>For all</i>
From centre of disc to top of statutory deck line { at awning or part awning deck	<i>13</i>	ft.	<i>1 1/2</i>	ins.	<i>Reasons</i>
shelter deck Fresh water line above centre of disc			<i>✓</i>	ins.	
Indian Summer line above centre of disc			<i>✓</i>	ins.	
Winter line below centre of disc			<i>✓</i>	ins.	
Winter North Atlantic line below centre of disc			<i>✓</i>	ins.	
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood on deck with the vessel's side {					
at main, spar or upper dk.				ins.	
at awning or pt. awning dk. <i>shelter deck</i>			<i>1 1/2</i>	ins.	

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or ~~iron~~ deck.*From wood deck**S. D. Cushman* Surveyor.

(To be filled up in London Office.)

Statement No. *25902* Date of Committee's Minute *18.6.18*Moulded Depth for record *40* ft. *9* ins.Freeboards compared and found correct by *SKM* date *17.6.18*Is fee paid? *Yes*Form for Certificate *A*Instructions *Write Certificate & Post.*date *18.6.18*Certificate written *18-6-18*Noted for posting *✓*