

F.E.

Received from Chief Ship Surveyor

by Chief Ship Surveyor

Rpt. Xia. No. 1994.

SEL'S NAME Steel SS "SORKA"

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 35.5 Depth "d" 12.92'
 Spacing: Table No. 3 Description Single angle as approved.
 Longitudinal No. 387B. Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{7.8}{}$
~~Back~~ Sheerstrake as approved.

The vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A.1. (steel) as recommended.

1 DK. (pk str - ws).

DTA 7' 7b.

BK. 8" 3 BH. ccm. Lloyd's A+C.P.

Date of Build 8, 17.

M. AEB.
17.2.20

It is included a spare tiller ^{Labels} ~~Labels~~ been supplied, but the Surveyors should be requested to state if this is so.



© 2020

Lloyd's Register Foundation

006809.006818.0074