

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

S.S. ODIN

Rpt.

Chm

No.

7286

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Transverse No.

2462

Depth "d"

14.42 &amp; 13.25

Framing: Table No.

✓

Description

Bull angle framing

Longitudinal No.

6762

Proportions

Length

Depth =

9.93

Deck Sheerstrake

As approved.

Revised rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\star$  100A.1. (stul) For Fishery Inspection Services.

$\star$  100A.1. (stul)  
For Fishery Inspection Services

1 dk (stl - ws) & 2<sup>nd</sup> dk forward raft.  
Cell DB & 22' 20t. DTs & 40t & 17t FPT 10t.  
BK 7" 4 BH. Cam  
Lloyd A & CP F 27'



2020  
Lloyd's Register  
Foundation

006819-006830-0134