

REPORT of SURVEY for REPAIRS, &c.

DECLASSIFIED
BOX No. 151

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

33818 on the Wood, Iron or Steel *Simcolite* *Imperial* *Simcoe*

TONNAGE: Built at *Herbert Hill on Is* By whom *James S.B. Cold* When *1930*

GROSS *1919* Owners *Imperial Oil Co* Owners' Address

UNDER DK *1465* Managers *H.J. Rahves* Port belonging to *Montreal*

NET *1085*

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER: * for Special Survey. Date of last survey and of Periodical Surveys. Machinery and Boiler Surveys (including date of N.B., if any).

+ 100A / H. 30 + LMC 4 30
For service on the Great Lakes
Fitted for oil fuel H. 30 etc
Banyon pit - bulk

Last Report, No. 14039 Port *Mdb*

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	DK. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month.
Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Caulking of Decks	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Stowings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained.
Rigings & Fastenings	Cement or Asphalt (State which.)	Oil Bunkers	(State if wedges removed)
Outside Plating	Rudder	Scuppers	Sails
Stanchions	Steering gear and its connections	Cargo Hatchways	Equipment letter
Stanchions	Windlass	Hatches	Anchor, No. of
Stanchions	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Chain Locker
Stanchions	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now on board)
Stanchions	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Rule length
Stanchions	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems ditto	Hawser & Warps
Stanchions		Transoms Pointers, & Crutches ditto	Standing and Running
Stanchions		Timbers of Frame at openings ditto	
Stanchions		Ditto Ditto at other places ditto	
Stanchions		Stringers, Clamps & Shelves ditto	
Stanchions		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute
Character Assigned
AUG 1936
Withdraw Class
insert...
General Committee
Thursday 13th

