

1E

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME

Komaki Manu.

Rpt.

Kobe

No.

8433

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

e of Engine

Oil Engines

2. S.C.D.A.

If Boilers fitted with forced draught

No

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of }
approved type

No.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ Linc. 12.33.

O.B. 100 lb.

Handwritten signature
30.1.34
Handwritten signature



© 2021

Lloyd's Register
Foundation

006857-006867-0270