

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

THU. AUG. 14. 1913

23018

3480

Port

Gusto

(When received in London Office)

Vessel's Name

Belvedere

Official No.

No. in Reg. Book

Port of Registry (For Foreign Vessels)

Gusto

Iron or Steel

Steel

State whether Classed by Lloyd's Register

Yes

Name of Owners

Unione Austriaca

Date of Verification

12/8/13

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line 8 ft. 7 1/2" ins. ✓

From centre of disc to top of statutory deck line }
at awning or part-awning deck . . . } ft. . ins.

Fresh water line above centre of disc . . . 7 ins. ✓

Indian Summer line above centre of disc . . . 6 1/2 ins. ✓

Winter line below centre of disc . . . 6 1/2 ins. ✓

~~Winter North Atlantic line below centre of disc~~ ✓ ins.Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side {
at main, spar or upper dk. 1 3/4 ins. ✓
at awning or pt.-awning dk. ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

Surveyor.

(To be filled up in London Office.)

Statement No 23018 Date of Committee's Minute

6.8.13

Moulded Depth for record

37 ft. 0 ins.

Freeboards compared and found correct by

M.C.

date 14.8.13

Is fee paid?

how vessel

Form for Certificate

Instructions

Write Certificate & Post.

date

14.8.13

Certificate written

14/8/13

Noted for posting