

pressure as per
e test pressure:
or valves fitted

Tested by hydraulic pressure to 350 lb Date of test 12/13/33 No. of Certificate 523/4 Can each boiler be worked at
Area of Firegrate in each Boiler 54.5 sq ft No. and Description of safety valves to each boiler 1 pair spring

Boilers
Boiler No. _____ Made by Kranjcar W.A.
S. Jugoslavija
Report No. 87000

It is submitted that a copy of Sent this Report be returned to
the Susak Surveyors for their guidance and
for completion.

Date 12/4/37

Tube plates: Material { front Steel
back _____ Tensile strength { 26 | 30 T
lean pitch of stay tubes in nests 9 3/8" Pitch across wide water spaces 13 3/4" | 3 3/4"
Risers to combustion chamber _____ Working pressure _____

© 2021 Lloyd's Register Foundation