

NAME **SS AGNES**
 Class **+100 A1.**
 Class records: *no later survey reported (7.41)* Cargo Batters not fitted.
 Hull **SS. lts. 2nd. no 3. 1-37.**
 Machinery **MS. 1.37.** Tail shaft **1.39 C.L.**
 Boiler **8.39 Mr Y. gives 1.40.** Donkey Boiler **—**
 S.R. List **—**

Survey held at **Helsingfors.** Report **Hfs. 1908** Date **June 41.**
 Hull **SS. no. 1.** and ice collision and grounding damages.

Machinery **L.M.C. 5.41.** Tail shaft **C.L. 5.41**
 Boiler **(P. 2.41 S. 3.41).** Donkey Boiler **— D.B. removed**
 S.R. List **—**
 Remarks **To complete S.S. lower coal bunkers to examine.**
BS due 2.42

RECOMMENDATION to Classing Sub-Committee:
 Enquire re BS. due 3.42 completion of SS. no. 1.

Eligible to remain as now classed *Hull Yes. } delete "no later survey reported"*
Yes. } later survey reported (BS)
Col. 13 Delete D. Blr pressure and NOB. 28

Fresh records:
 Hull **SS. Hfs. no 1-41 when survey completed.** Docking date **Hfs. 5.41**
 Machinery **MS 5.41** Tail shaft **CL 5.41**
 Boiler **BS 8.41** Donkey Boiler **—**

S.R. List **To complete S.S. lower coal bunkers to ex. Hfs.**

Approved by Committee

27.8.42.

Name of Managers changed



© 2021

Lloyd's Register
 Foundation