

"Agnes" "Agie"

F.E.

Received by Chief Ship Surveyor 13/3/19

Received from Chief Ship Surveyor

VESSEL'S NAME *At H "Oostdijk"*

Rpt. *Rok*

No. *7671*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *71.16*

Depth "d" *20.11*

Framing: Table No. *Page 11*

Description *Bull angle*

Longitudinal No. *23/27*

Proportions Length = *10. H<sup>3</sup>*  
Depth =

*Bridge Deck Sheerstrake 04 less in thickness than required by Rule but compensated by Bull angle frames to give equivalent strength.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *± 100 A.1. (Steel)* as recommended

*± 100 A.1. (Steel)*

*10<sup>th</sup> (Steel)*

*WB = Lou & Ba 90 u 82i f 150 6986 APT 774*

*FK. SBH 6m Lloyd AT 60 P2i 89i F3i*

