

5m,9,24.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_ 4 - DEC 1925

VESSEL'S NAME Stl. s.s. "PANAGHIS VERGOTTIS". Rpt. Hul. No.36588

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

The class of this vessel is subject to indented plating etc., being dealt with at the Owners' convenience.

The Hull Surveyors now report the vessel placed in dry dock, bottom cleaned and coated.

The indented plating has been examined and found satisfactory.

It is submitted the vessel appears worthy to remain as classed with record of survey 11-25, subject as above.

100 A1

11.75 Hue

} Subject to



© 2020

3.12.25.

Lloyd's Register  
Foundation

007100 - 007115 - 0019