

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes
Done

, and of the Donkey Boil

S. S. "Seattle"

H.W.C. 72858
72859

This vessel was built at Newcastle in 1911, not under the survey of this Society. The machinery and boilers have been opened up for examination and the first entry report received, from which it appears the particulars of the machinery and boilers comply with the rules and requirements of this Society for a working pressure of 180 lbs. The screw shaft fitted with a continuous liner has been examined and found satisfactory.

It is submitted that this vessel is eligible for

THE RECORD

L.M.C. 2.20 F.D.

S. 2.20

J.W.D.



© 2020
J.W.D.

13/3/20

veral Observations, Opinion, and Recommendation
late clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery
any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for
140 lbs., F.D., &c.)

007139 - 007149 - 0214