

FREEBOARD VERIFICATION FORM FOR ORDINARY CARGO ^{AND}_{OR} PASSENGER SHIPS.

05QA.

When received in London Office

Port Antwerp

Name S.S. 'Katanga'

Official No. _____ No. in Reg. Book _____

Port of Registry Antwerp Gross Tonnage 5183 Signal Letters _____

Iron or Steel _____ State whether Classed by Lloyd's Register + 100 A 1

Name of Owners _____ Date of Verification _____

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

| FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE, WOOD /STEEL DECK. | | | FROM CENTRE OF DISC. |
|--|----------|----------------------|------------------------------|
| Tropical Fresh Water | 1478 ft. | $\frac{22}{16}$ ins. | 334 $\frac{1}{2}$ ins. above |
| Fresh Water | 1637 ft. | " ins. | 175 ins. above |
| Tropical | 1653 ft. | " ins. | 159 ins. above |
| Summer | 1812 ft. | " ins. | |
| Winter | 1971 ft. | " ins. | 159 ins. below |
| Winter North Atlantic | " ft. | " ins. | " ins. below |

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:—

Surveyor.

(To be filled up in London Office.)

Statement No. 25434 Date of Committee's Minute _____

| | | | |
|---|---------------------------------|-----|------|
| Particulars for Record in Register Book. | Moulded Depth | ft. | ins. |
| | Freeboard | ft. | ins. |
| | Corresponding Draught | ft. | ins. |

Freeboards compared and found correct by _____ Date _____

Is fee paid? _____

Form for Certificate _____

Certificate written _____

Noted for posting _____