

1E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

Vessel's NAME

Beccelita

Rpt.

 Hll. No. 4608  
 Clv. No. 866  
 Ver. " 4760  
 4981

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Type of Engine

 Oil Engines 2 S.C.S.A.  
 5-Cyl. 14"—17"
~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

 If fitted with an outside gland of  
 approved type

 Yes  
 No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  LMC 12.37. subject to the electrical equipment being placed in order.  
 (See endorsement dated 6/1/39.)

States correspondence

Note part-engine survey.

 L.F.  
 11/1/39.


© 2021

 Lloyd's Register  
 Foundation

007246 007256 0299