

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

St. J. J. Glatian

Rpt

*Lynn
Jul*

No

*2067
20576*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

33.02

Depth "d"

10.92

Framing: Table No.

3 page 9

Description

Single angle as

Longitudinal No.

H035

approved

Proportions

Length

Depth

= 9.79

~~Deck~~ Sheerstrake *50 in lieu of 34 as required*

The Grimsby Surveyors report that the machinery has been fitted at their port & the E & B casings have been efficiently closed in, & the masts & rigging fitted.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to

be classed **+** 100 A.1. (Stub) Steam Trawler, as recommended.

+ 100 A.1. (Stub) Steam Trawler

1872

BK 7 1/2 H.B.H. Gen Lloyd, at 60 Q69 F20

M
2/9/13

