

offered his services for this purpose, and why they were declined

2E

inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Kachisan Maru

Rpt. Robe.

No. 9555

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/24)

Subject of Survey: COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 1

This Survey, due 1235 <sup>now</sup> ~~partly held~~ <sup>held</sup> now

completed, ~~and the following repairs carried out (due to~~ ):-


An additional electric generator set fitted.

It is submitted the vessel is eligible to remain as classed, with

notation of ~~five at 4.36~~ as recommended.

five at 4.36  
4.36.

two at 4.36



© 2021

Lloyd's Register Foundation

27/9/36

007352-007362-0083

The following parts of the machinery opened up for survey, examined and for