

Less Crew Space  
Less above Crown of  
Engine Room ...  
Tons  
Less

on 11.12

1

Britannica

Sent to Chief Surveyors

26/4/13

Received from Chief Surveyors

VESSEL'S NAME

SS 'Doon'

Report

Liv

No. 69371

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

+ A.I. ("Old") For River purposes only  
Dr.

WB. Hull DB a 70 f 52 3006 PPT 75L

FR<sup>5BA</sup> Gen. Lloyd A & B 34 F 166 XXXX XXXX

M

721311

26/4/13



© 2020

Lloyd's Register  
Foundation

007396-007402-0242