

be seen. Sound

C. Fremont 26.

Rot. 15418.

Submitted the Surveyors be requested to state the smallest distance between Boilers or plates & braked or woodwork.

It is concluded that the safety valves were adjusted to 180 lbs. & are fitted with easing gear & that there are 3 bilge sections & a direct bilge section in the machinery space as shown on the approved plan, but this should be confirmed.

Lr 678726

R.A. 5/8/26.

RA

Shilling 1000
before fracture ...

When Inspected

24/8/1925

F

2/12/1925

007422-007431-0096

Wor