

Mrs. Marumula Brw. rept. 1894.
on Twin Diesel Engine.

These engines have been taken out of above vessel, & new Diesel Engines by Werkspoor, Amsterdam*, Substituted. This fact has been recorded on the Machinery Index Card under the heading of Vickers, Ltd. If these engines detailed in this report are subsequently fitted on board a classed vessel, this document should be attached to the 'fitting on board' report.

X. Ams report No. 11010,
on Trizonia
(ex Marumula)

© 2021
J.M.
18.6.98
Lloyd's Register
Foundation

007432-007438-0017

Is the ballast pump fitted with a direct suction from the engine room bilges Yes—

State size

6

Is a sep

Are the roses in Engine