

3m. 8. 21.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S. S. 'DELAWARE SUN'

Report

Pl

No.

4318

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

❖ 100-A-1. (Steel) Shelter Deck with foreboard
Carrying petroleum in bulk

1 Dk (Steel) v Shelter Dk (Steel) v Webframes, longitudinal framing

Cell 2B v E v 13 ft 40' 39st, FPT 186t, APT 84t

FK; 19BH (9 to Shelter Dk, 10 to Upper Dk); pt Cen; A v CP;
F 44' on Shelter Dk; 11ch. Aff.



© 2021

Lloyd's Register
Foundation

007528-007536-0123

(Corresponding Draught

26

11.

11

118.

No. 11